## EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

Scope of Work for Property Located at: 2909 North 22nd Street Property is: Single Family Duplex □ Other 5/12/2021 OCCUPIED City prepared this Scope upon visual inspection only, for limited purpose. City does not warrant content or conclusions, and is not responsible for errors, omissions, or discovery of conditions that are or may constitute defects or concerns ESSENTIAL REPAIRS. All buyers must complete Essential Repairs and obtain "Essential Repair Verification Form" and provide same to DCD within 180 days of City's deed to buyer in order to get return of performance deposit. Note/Comments Required Work Cost Location **Entire Building** n/a □ Yes □ Structural Violations \$ Defective/Missing HVAC n/a Yes 🗵 \$ Boiler, radiatiors and supply pipes damaged or missing. 9.000.00 Repair/replace all or install other HVAC method. HVAC permit required. (estimated cost is for installing forced air Defective/Missing Plumbing Sewer back up in basement. Water heater missing. Unable to \$ n/a □ Yes 🔽 10.500.00 verify existence of water meter due to sewer back up. Supply, drain and vent pipes missing or damaged. Missing or damaged fixtures in kitchen and bathroom. Clear main sewer drain and repair all other plumbing to code compliant condition. Plumbing permit required. Defective/Missing Electrical Yes 🔽 \$ n/a □ Panel tampered with and all branch wires cut. Missing or 9,000.00 broken fixtures, switches and receptacles throughout. Repair all electrical to code compliant condition. Electrical nermit required Defective/Missing Egress n/a □ Yes \$ n/a 🛚 \$ Defective/Missing Smoke/CO Alarm Yes 🗹 Required per code throughout. 250.00 Repair significant peeling paint and broken plaster 4 Repair Defective Paint (Interior) n/a Yes 3,500.00 throughout Defective/Missing Roof (Major) Tearoff and replace roof. Includes gutters & downspouts. \$ 11,500.00 n/a 🔲 Yes 🔽 Missing Window(s) n/a 🛚 Several units broken or missing. Repair/replace all. 2,000.00 \$ Missing Exterior Door(s) n/a □ Repair replace all exterior doors to operational condition. 600.00 Yes 🛂 \$ n/a 🔲 Yes \$ Essential Repairs: Estimated Cost:\* 46,350.00 Lead (Pb) orders from MHD exist and must be \$ completed with other essential repairs. \*average contracted cost. Actual costs may vary. Self help will reduce the amount. OTHER REPAIRS (Exterior & Interior). Buyer is notified that the following are code violations that must be addressed and are subject to Department of Neighborhood Services (DNS) enforcement. **Exterior Condition Report** Location Required Work Note/Comments Cost n/a □ Yes 🗹 Site Landscaping \$ 200.00 Steps/Handrails n/a □ Yes \$ \$ 1,250.00 Service walks n/a 🔲 Yes 🛂 Fencing n/a 🔲 Yes 🗌 \$ Parking n/a □ Yes ☑ \$ 4,000.00 Retaining walls n/a 🗌 Yes 🛂 \$ 500.00 Other Yes \$ n/a □ n/a 🔲 Other Yes \$ Garage Singles: repair n/a □ Yes □ \$ Shingles: Roof over existing n/a 🔲 Yes 🗌 \$ Shingles:Tear off & re-roof \$ n/a □ Yes □ Gutters/downspouts n/a □ Yes \$ n/a □ Yes Flashing \$ n/a □ Yes 🗌 \$ Eaves Siding n/a 🗌 Yes \$ Doors n/a 🗌 Yes 🗌 \$

Garage (Cont Windows		n/a □ Yes □	\$
Porches	Slab	n/a □ Yes □	\$
	Paint	n/a □ Yes □	\$
	Electrical	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$
	Roof	n/a □ Yes □	\$
	Deck-upper	n/a □ Yes □	\$
	Decklower	n/a □ Yes □	\$
	Steps/handrails	n/a □ Yes ☑	\$ 750.00
	Ceiling	n/a □ Yes □	\$
	Guardrails	n/a □ Yes □	\$
	Structural	n/a □ Yes □	\$
	Paint	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$
House	Chimney	n/a □ Yes □	\$
	Shingles: repair	n/a □ Yes □	\$
	Shingles: Roof over existing	n/a □ Yes □	\$
	Shingles:Tear off & re-roof	n/a □ Yes □	\$
	Gutters/downspouts	n/a □ Yes □	\$
	Flashing	n/a □ Yes □	\$
	Eaves	n/a □ Yes □	\$
	Siding	n/a □ Yes □	\$
	Storm Doors	n/a □ Yes □	\$
	Prime ("main") Doors	n/a □ Yes □	\$
	Storm Windows	n/a □ Yes □	\$
	Prime ("main") Windows	n/a □ Yes □	\$
	Paint	n/a ☐ Yes ☑ <b>Eaves</b>	\$ 1,200.00
	Foundation	n/a □ Yes □	\$
	Electrical	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$
	Other	n/a □ Yes □	\$

Exterior: Estimated Cost:\*
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

7,900.00

Interior Condition Report								
	Unit: Entire unit (single family)	Ø		Lower unit of duplex				
Mechanical R	Upper unit of duplex Required Work			Other				
Heating	•							
	Repair/replace boiler	n/a □	Yes ☑	See essential repairs	\$			
	Repair radiation	n/a 🗌	Yes 🗌		\$			
	Repair/replace furnace	n/a 🗌	Yes 🗌		\$			
	Repair ductwork	n/a □	Yes □		\$			
	Replace thermostat	n/a □	Yes □		\$			
	Repair/replace grilles	n/a □	Yes □		\$			
Electrical	Tune boiler/furn. insp ht exchanger	n/a 🗌	Yes 🗌		\$			
Licotrical	Repair/replace receptacles	n/a □	Yes □		\$			
	Repair/replace switches	n/a □	Yes □		\$			
	Repair/replace fixtures	n/a □	Yes □		\$			
	Install outlets and circuits	n/a □	Yes □		\$			
	Install outlets and circuits	n/a □	Yes □		\$			
	Install outlets and circuits	n/a 🗌	Yes 🗌		\$			
	Install outlets and circuits	n/a □	Yes □		\$			
	Upgrade service	n/a □	Yes 🗆		\$			
	Other	n/a □	Yes 🗹	See essential repairs	\$			
Plumbing	Other	n/a □	Yes □		\$			
Fluilibility	Repair/replace kitchen sink	n/a □	Yes □		\$			
	Repair/replace kitchen sink faucet	n/a □	Yes □		\$			
	Repair/replace tub	n/a □	Yes 🗆		\$			
	Repair/replace tub faucet	n/a □	Yes 🗌		\$			
	Repair/replace toilet	n/a □	Yes □		\$			
	Repair/replace lavatory	n/a □	Yes □		\$			
	Repair/replace lavatory faucet	n/a □	Yes □		\$			
	Repair/replace wash tub	n/a □	Yes □		\$			
	Repair/replace wash tub faucet	n/a □	Yes □		\$			
	Unclog piping:	n/a □	Yes 🗆		\$			
	Repair drain/waste/vent piping	n/a □	Yes □		\$			
	Repair water piping	n/a □	Yes □		\$			
	Repair/replace water heater	n/a □	Yes □		\$			
	Other	n/a □	Yes ☑	See essential repairs	\$			
	Other	n/a □	Yes □		\$			

Windows					
	Replace broken glass	n/a □	Yes ☑	See essential repairs	\$
_	Repair or replace sash	n/a □	Yes 🗌		\$
Doors	Repair or replace doors	n/a □	Yes 🗹		\$ 1,000.00
	Repair or repl. locks/latches	n/a □	Yes ☑		\$ 250.00
Walls/Ceiling					
	Repair or repl. @ defective	n/a 🗌	Yes <b></b> ✓	See essential repairs	\$
Fire Safety	Install smoke/CO alarm:bsmt.	n/a □	Yes ☑	See essential repairs	\$
	Install smoke/CO alarm: 1st flr.	n/a □	Yes ☑	See essential repairs	\$
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes 🗹	See essential repairs	\$
Handrails	Repair/replace defective	n/a □	Yes ☑		\$ 200.00
Stairs	Repair defective	n/a □	Yes ☑		\$ 500.00
Floors	Repair defective	n/a □	Yes ☑		\$ 3,000.00
Other		n/a □	Yes □		\$
		n/a □	Yes 🗆		\$
		n/a □	Yes 🗆		\$
		n/a □	Yes 🗆		\$
				Interior: Estimated Cost:	\$ 4,950.00
	Total	\$ 59,200.00			

\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

## Inspected by: Jeff Sporer Date: 5/12/2021

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start.

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

 $\label{eq:continuous} Generally, \ minor \ carpentry \ repairs, \ plaster \ patching, \ and \ painting \ do \ not \ require \ permits.$ 

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 841 N. Broadway, 1st Floor.

There may be bare soil at this premises. This soil may have accumulated lead in amounts greater than or equal to the US Environmental Protection Agency (EPA) Lead in Soils Standards. For advice on addressing lead in soil, consult the document <a href="https://document-bluman-Health-Hazards: Lead in soil from exterior paint">https://document-bluman-Health-Hazards: Lead in soil from exterior paint</a> from the State of Wisconsin at <a href="https://www.dhs.wisconsin.gov/publications/p45015.pdf">www.dhs.wisconsin.gov/publications/p45015.pdf</a> .