

EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

Scope of Work for Property Located at: 1519 North 38th Street

Property is: Single Family Duplex Other

Date: 1/14/2020 OCCUPIED VACANT

City prepared this Scope upon visual inspection only, for limited purpose. City does not warrant content or conclusions, and is not responsible for errors, omissions, or discovery of conditions that are or may constitute defects or concerns

ESSENTIAL REPAIRS. All buyers must complete Essential Repairs and obtain "Essential Repair Verification Form" and provide same to DCD within 180 days of City's deed to buyer in order to get return of performance deposit.

Location Entire Building	Required Work		Note/Comments	Cost
	Structural Violations	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Defective/Missing HVAC	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Basement inaccessible. Repair/replace furnace & ductwork as needed to operable condition. HVAC permit required for any new work.	\$ 3,500.00
	Defective/Missing Plumbing	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Basement inaccessible. Repair/replace water heater, water meter, supply, drain and vent pipes as needed. Plumbing permit required for any new work.	\$ 3,000.00
	Defective/Missing Electrical	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Meter tampered with. Basement inaccessible. Repair/replace panel to operable condition. Electrical permit required.	\$ 2,500.00
	Defective/Missing Egress	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Defective/Missing Smoke/CO Alarm	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Required per code throughout	\$ 250.00
	Repair Defective Paint (Interior)	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Peeling & missing paint assorted areas. Repair all. Includes repairing any broken or missing plaster.	\$ 2,000.00
	Defective/Missing Roof (Major)	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Replace entire roof.	\$ 11,500.00
	Missing Window(s)	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Several missing or broken	\$ 2,500.00
	Other	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Replace missing guardrails on 2nd floor rear porch	\$ 1,500.00
	Other	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	Repair/replace front porch decking	\$ 1,250.00
Essential Repairs: Estimated Cost:*				\$ 28,000.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

OTHER REPAIRS (Exterior & Interior). Buyer is notified that the following are code violations that must be addressed and are subject to Department of Neighborhood Services (DNS) enforcement.

Exterior Condition Report

Location Site	Required Work		Note/Comments	Cost
	Landscaping	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Steps/Handrails	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Service walks	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Fencing	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Parking	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Retaining walls	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Other	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Other	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
Garage	Singles: repair	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Shingles: Roof over existing	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Shingles:Tear off & re-roof	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>		\$ 3,500.00
	Gutters/downspouts	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Flashing	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Eaves	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Siding	n/a <input type="checkbox"/> Yes <input type="checkbox"/>		\$
	Doors	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>		\$ 450.00
	Windows	n/a <input type="checkbox"/> Yes <input checked="" type="checkbox"/>		\$ 600.00

Garage (Cont)	Slab	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Paint	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	\$ 2,500.00
	Electrical	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Porches	Other	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	Repair leaning walls to plumb and straight. \$ 2,000.00
	Roof	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Deck-upper	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Deck-lower	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	See essential repairs \$
	Steps/handrails	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Ceiling	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Guardrails	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Structural	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Paint	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	\$ 1,500.00
	Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
House	Chimney	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	\$ 500.00
	Shingles: repair	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Shingles: Roof over existing	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Shingles:Tear off & re-roof	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	See essential repairs \$
	Gutters/downspouts	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	\$ 1,250.00
	Flashing	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Eaves	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Siding	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Storm Doors	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Prime ("main") Doors	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Storm Windows	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Prime ("main") Windows	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Paint	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	\$ 3,000.00
	Foundation	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Electrical	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
	Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$	
Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$	

Exterior: Estimated Cost:* \$ 15,300.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Condition Report

Unit: Entire unit (single family) Lower unit of duplex
 Upper unit of duplex Other

Mechanical Required Work

Heating

Repair/replace boiler	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair radiation	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace furnace	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	See essential repairs
Repair ductwork	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Replace thermostat	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace grilles	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Tune boiler/furn. insp ht exchanger	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$

Electrical

Repair/replace receptacles	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace switches	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace fixtures	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Install outlets and circuits	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Install outlets and circuits	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Install outlets and circuits	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Install outlets and circuits	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Upgrade service	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Other	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	See essential repairs
Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$

Plumbing

Repair/replace kitchen sink	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace kitchen sink faucet	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace tub	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace tub faucet	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace toilet	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace lavatory	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace lavatory faucet	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace wash tub	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace wash tub faucet	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Unclog piping:	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair drain/waste/vent piping	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair water piping	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Repair/replace water heater	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$
Other	n/a	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/>	See essential repairs
Other	n/a	<input type="checkbox"/>	Yes	<input type="checkbox"/>	\$

Windows

Replace broken glass n/a Yes \$

Repair or replace sash n/a Yes \$

Doors

Repair or replace doors n/a Yes \$

Repair or repl. locks/latches n/a Yes \$

Walls/Ceilings

Repair or repl. @ defective n/a Yes **See essential repairs** \$

Fire Safety

Install smoke/CO alarm:bsmt. n/a Yes **See essential repairs** \$

Install smoke/CO alarm: 1st flr. n/a Yes **See essential repairs** \$

Install smoke/CO alarm: 2nd flr. n/a Yes **See essential repairs** \$

Handrails

Repair/replace defective n/a Yes \$ **100.00**

Stairs

Repair defective n/a Yes \$ **250.00**

Floors

Repair defective n/a Yes \$ **500.00**

Other

n/a Yes **Replace missing guardrail on basement steps** \$ **750.00**

n/a Yes \$

n/a Yes \$

n/a Yes \$

Interior: Estimated Cost: \$ 1,600.00

Total Essential Repairs, Exterior, and Interior Cost:* **\$ 44,900.00**

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by Jeff Sporer

Date: 1/14/2020

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start.

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants *may* be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants *may* be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 841 N. Broadway, 1st Floor.

There may be bare soil at this premises. This soil may have accumulated lead in amounts greater than or equal to the US Environmental Protection Agency (EPA) Lead in Soils Standards. For advice on addressing lead in soil, consult the document [Human Health Hazards: Lead in soil from exterior paint](http://www.dhs.wisconsin.gov/publications/p45015.pdf) from the State of Wisconsin at www.dhs.wisconsin.gov/publications/p45015.pdf.