EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

3320 West Clybourn Street

Scope of Work for Property Located at:

Property is: Single Family Duplex □ Other 5/12/2021 OCCUPIED 🗵 VACANT City prepared this Scope upon visual inspection only, for limited purpose. City does not warrant content or conclusions, and is not responsible for errors, omissions, or discovery of conditions that are or may constitute defects or concerns ESSENTIAL REPAIRS. All buyers must complete Essential Repairs and obtain "Essential Repair Verification Form" and provide same to DCD within 180 days of City's deed to buyer in order to get return of performance deposit. **Note/Comments** Cost **Location Required Work Entire** Building Yes 🗆 n/a □ Structural Violations \$ n/a Yes \$ Defective/Missing HVAC Defective/Missing Plumbing n/a □ Yes \$ Defective/Missing Electrical n/a 🗌 Yes \$ Yes 🗆 Defective/Missing Egress n/a 🛚 \$ Defective/Missing Smoke/CO Alarm n/a □ Yes \$ Repair Defective Paint (Interior) n/a 🔲 Yes 🗵 \$ 1,500.00 Defective/Missing Roof (Major) n/a 🔲 Yes 🛂 \$ 13,000.00 Missing Window(s) n/a □ Yes 🗵 \$ 9,600.00 missing/damaged/boarded/original windows/lead abatement n/a □ Missing Exterior Door(s) Yes \$ Yes Other \$ n/a □ Essential Repairs: Estimated Cost:* \$ 24,100.00 ☐ Lead (Pb) orders from MHD exist and must be completed with other essential repairs. *average contracted cost. Actual costs may vary. Self help will reduce the amount. OTHER REPAIRS (Exterior & Interior). Buyer is notified that the following are code violations that must be addressed and are subject to Department of Neighborhood Services (DNS) enforcement. **Exterior Condition Report** Location Required Work Note/Comments Cost n/a □ Yes Self Help Site Landscaping \$ Steps/Handrails n/a □ Yes \$ Service walks n/a 🔲 Yes 🗆 \$ Yes 🗆 n/a 🛚 \$ Fencing Parking n/a 🗌 Yes ☑ \$ 3,000.00 Yes 🗌 Retaining walls n/a □ \$ Yes \$ Other n/a 🔲 n/a 🛚 Other Yes \$ Garage Singles: repair n/a □ Yes \$ Shingles: Roof over existing n/a □ Yes \$ Shingles:Tear off & re-roof n/a 🔲 Yes \$ Gutters/downspouts n/a 🔲 Yes 🗌 \$ n/a 🔲 Yes 🗌 \$ Flashing Eaves n/a 🗌 Yes \$ n/a □ \$ Siding Yes n/a □ Yes \$ Doors Windows n/a □ Yes \$ n/a 🗌 \$ Slab Yes 🗌 Paint n/a 🔲 Yes \$ Electrical n/a Yes 🗌 \$ Other n/a 🔲 Yes 🗌 \$

Porches

House

Roof	n/a □ Ye	s 🗷		\$ 3,500.00
Deck-upper	n/a □ Ye	s 🛮		\$
Decklower	n/a □ Ye	s 🗆		\$
Steps/handrails	n/a □ Ye	s 🗆		\$
Ceiling	n/a □ Ye	s 🗹		\$ 1,000.00
Guardrails	n/a □ Ye	s 🛮		\$
Structural	n/a □ Ye	s 🗆		\$
Paint	n/a □ Ye	s u		\$ 1,500.00
Other	n/a □ Ye	s 🗆		\$
Chimney	n/a □ Ye	s 🗆		\$
Shingles: repair	n/a □ Ye	s 🛘		\$
Shingles: Roof over existing	n/a □ Ye	s 🛘		\$
Shingles:Tear off & re-roof	n/a □ Ye	s 🗆		\$
Gutters/downspouts	n/a □ Ye	s 🗸		\$ 2,000.00
Flashing	n/a □ Ye	s 🛘		\$
Eaves	n/a □ Ye	s 🗹		\$ 4,500.00
Siding	n/a □ Ye	s 🗹		\$ 2,500.00
Storm Doors	n/a □ Ye	s 🗆		\$
Prime ("main") Doors	n/a □ Ye	s 🗹		\$ 700.00
Storm Windows	n/a □ Ye	s 🗆		\$
Prime ("main") Windows	n/a □ Ye	s 🗆		\$
Paint	n/a □ Ye	s 🗹		\$ 3,500.00
Foundation	n/a □ Ye	s 🗆		\$
Electrical	n/a □ Ye	s 🛘		\$
Other	n/a □ Ye	s 🛘		\$
Other	n/a □ Ye	s 🗆		\$
Other	n/a □ Ye	s 🛘		\$
Other	n/a □ Ye	s 🗆		\$

Exterior: Estimated Cost:* \$ 22,200.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior	Condition Report Unit: Entire unit (single family)	4		Lower unit of duplex			
Mechanic Heating	Upper unit of duplex al Required Work			Other			
	Repair/replace boiler	n/a □	Yes □				\$
	Repair radiation	n/a □	Yes □				\$
	Repair/replace furnace	n/a □	Yes 🗵				\$ 750.00
	Repair ductwork	n/a □	Yes □				\$
	Replace thermostat	n/a □	Yes □				\$
	Repair/replace grilles	n/a □	Yes 🗆				\$
Electrical	Tune boiler/furn. insp ht exchanger	n/a 🗌	Yes 🗌				\$
Liectrical	Repair/replace receptacles	n/a □	Yes ☑			_	\$ 150.00
	Repair/replace switches	n/a □	Yes ☑				\$ 150.00
	Repair/replace fixtures	n/a □	Yes ☑				\$ 150.00
	Install outlets and circuits	n/a □	Yes □				\$
	Install outlets and circuits	n/a □	Yes □				\$
	Install outlets and circuits	n/a 🗌	Yes 🗌				\$
	Install outlets and circuits	n/a □	Yes 🗆				\$
	Upgrade service	n/a □	Yes □				\$
	Other	n/a □	Yes ☑	resecure panel co	over		\$ 100.00
Diumbina	Other	n/a □	Yes □				\$
Plumbing	Repair/replace kitchen sink	n/a □	Yes ☑	drain plumbing			\$ 300.00
	Repair/replace kitchen sink faucet	n/a □	Yes □				\$
	Repair/replace tub	n/a □	Yes 🗹	surround			\$ 1,700.00
	Repair/replace tub faucet	n/a 🗌	Yes 🗌				\$
	Repair/replace toilet	n/a □	Yes ☑				\$ 300.00
	Repair/replace lavatory	n/a □	Yes 🗆				\$
	Repair/replace lavatory faucet	n/a □	Yes □				\$
	Repair/replace wash tub	n/a □	Yes □				\$
	Repair/replace wash tub faucet	n/a □	Yes 🗆				\$
	Unclog piping:	n/a □	Yes 🗆				\$
	Repair drain/waste/vent piping	n/a □	Yes □				\$
	Repair water piping	n/a □	Yes □				\$
	Repair/replace water heater	n/a □	Yes 🗆				\$
	Other	n/a □	Yes ☑	reinstall main me	ter		\$ 750.00
	Other	n/a □	Yes □				\$

Total Essential Repairs, Exterior, and Interior Cost:*				
		\$	5,175.00	
Yes 🗆		\$		
Yes 🗌		\$		
Yes 🗌		\$		
Yes 🗆		\$		
Yes 🗆		\$		
Yes 🗆		\$		
Yes ☑		\$	150.00	
Yes 🗌		\$		
Yes 🗆		\$		
Yes □		\$		
Yes 🗌		\$		
Yes ☑		\$	165.00	
Yes ☑		\$	510.00	
Yes 🗌		\$		
Yes 🗌		\$		

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by: Nikolas Stoehr Date: 5/12/2021

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 841 N. Broadway, 1st Floor.

There may be bare soil at this premises. This soil may have accumulated lead in amounts greater than or equal to the US Environmental Protection Agency (EPA) Lead in Soils Standards. For advice on addressing lead in soil, consult the document https://document-bluman-Health-Hazards: Lead in soil from exterior paint from the State of Wisconsin at www.dhs.wisconsin.gov/publications/p45015.pdf .