

## MHD Contractor Performance: Second Quarter (April – June) 2017

CONTRACTOR	PREVENTION UNITS COMPLETED <sup>1</sup>	LEAD POISONED CHILD UNITS COMPLETED <sup>2</sup>	PERCENT OF RE-WIPES TAKEN <sup>3</sup>	LEAD SAFETY VIOLATIONS ISSUED	PERMIT EXTENSIONS <sup>4</sup>	OPEN COMPLAINTS
<b>C &amp; E CONSTRUCTION</b>	9	0	0.0%	0	0	NO
<b>MCM ENTERPRISES INC</b>	11	0	5.2%	1	0	NO
<b>EPM CONTRACTING</b>	2	0	0.0%	0	0	NO
<b>WEATHERIZATION SERVICES</b>	9	1	2.2%	0	0	NO
<b>FAQ HOME IMPROVEMENT LLC</b>	1	0	0.0%	1	0	NO
<b>GET HOME IMPROVEMENT LLC</b>	3	0	3.2%	0	0	NO
<b>BENITEZ, STEVEN</b>	5	0	3.8%	1	0	NO
<b>MEDINA, DAN</b>	6	0	0.0%	0	0	NO
<b>MODERN HOME IMPROVEMENT</b>	1	0	16.7%	0	0	NO
<b>RIGHT PRICE HOME IMPROVEMENT LLC</b>	1	0	0.0%	0	0	NO

1 – Includes all units monitored and cleared by MHD that received federal funding for voluntary lead abatement.

2 – Includes all units monitored and cleared by MHD that received private funding for ordered lead abatement due to a reported lead poisoned child.

3 – The number of additional required samples divided by the total number of samples taken for a contractor. At the end of a project, an inspector collects samples of the dust in the home. If a contractor leaves lead dust behind (as measured by laboratory analysis), the contractor must return to the property to preform additional cleaning on surfaces. The inspector then returns to the site to take additional samples (re-wipe) to confirm occupant safety.

4 – MHD granted the contractor additional time to complete a project beyond the initial two weeks period.