



Tom Barrett
Mayor

Bevan K. Baker, FACHE
Commissioner of Health

Joe'Mar Hooper, MPA
Health Operations Administrator

Health Department

www.milwaukee.gov/health

Frank P. Zeidler Municipal Building, 841 North Broadway, 3rd Floor, Milwaukee, WI 53202-3653 phone (414) 286-3521 fax (414) 286-5990
web site: www.milwaukee.gov/health

October 16, 2014

To whom it may concern,

Inspection conducted at **9308 W Capitol Dr. on 4-11-14**

1. Replace the kitchen exhaust hood as horizontal filters are not approved and the exhaust hood is too small for the equipment.
2. When the exhaust hood is replaced it will trigger the installation of steel studs, cement board and glued on stainless steel behind the new exhaust hood.
3. It will also cause the exhaust duct to be replaced along with the exhaust fans.
4. They will need to provide tempered make-up air.
5. Replace all the vinyl ceiling tiles with vinyl coated gypsum ceiling tiles in the kitchen.
6. Remove the gas hot holding unit as it needs to be under the exhaust hood and it is not.
7. Provide an additional hand sink on the west end of the kitchen.
8. If this would become a busy restaurant they would be required to install a dish machine with a clean end drain board along with possibly installing an exhaust hood for the dish machine. That would depend on which type of dish machine they may need.
9. Remove all wood from the floor along with particle board shelving use only stainless steel wire rack shelves in the bar.
10. Remove the plastic drawer unit from the bar also as it's not approved either.
11. The walk-in is for beverages only, not to be used for food.
12. Re-secure the FRP in the walk-in to the walls.
13. Remove the home style refrigerator from the premise, not approved.
14. Remove all unnecessary items from the basement.
15. Provide FRP to the wall behind the bag in the box soda.

Mark Malin

Equipment Specialist Supervisor

City of Milwaukee Health Department

414-286-5769

Think Health. Act Now!

